

SECRET

PRIORITY

19 NOV 1963

P 182034Z
FM CIA WASHDC
TO RUCSBR/SAC OFFUTT AFB, OMAHA, NEB
RUCVAB/4080 STRAT WG, OL 19, BARKSDALE AFB, LA
RUCVAB/2D RTS, BARKSDALE AFB, LA
RUEAHQ/DIAXX
RUECYG/NAVY PIC
RUWBKG/15TH AF, MARCH AFB, RIVERSIDE, CALIF
RUWGAA/2AF, BARKSDALE AFB, LA
DA GRNC
BT
S E C R E T

OUT 52314

1963 NOV 18 21 24Z

HFS TS
CJS TS
CFC TS
PHS TS
ACL TS

1

CITE CIA-Z-1019

15TH AF (FOR DI); SAC (FOR DIM, BRASS KNOB, DOCR, DM 4) 2D AF
(FOR DI). FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER. Grace (File)

1. CAMERA B 5 WAS USED IN MISSION 3772 FLOWN ON 14 NOVEMBER
1963; PROCESSING WAS ACCOMPLISHED BY NAVY PIC.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS FAIR
DUE TO THE ADVERSE WEATHER CONDITIONS THAT EXIST THROUGHOUT
THE MISSION.

B. 9R SIDE: A PLUS DENSITY STREAK 3.25" FROM AND PARALLEL
TO THE OUTBOARD EDGE IS CONTINUOUS THROUGHOUT THE MISSION.
PINHOLES ARE NUMEROUS AND CONCENTRATED ALONG AN AREA APPROXIMATELY
3" WIDE AT THE INBOARD EDGE. AN EXAMPLE MAY BE FOUND ON FRAME
533 WHERE 47 PINHOLES WERE COUNTED. EDGE FOG AND EMULSION
BLISTERS ARE MINOR AND INTERMITTENT THROUGHOUT THE MISSION.

SECRET

Declassification Review by NGA/DoD

Excluded from automatic
downgrading and
declassification

1

HEAT SPLICES ON FRAMES 452 AND 1114 APPEAR TO BE THE GENISSES OF INTERMITTENT TRANSVERSE, PLUS DENSITY BANDS FOR 50 FRAMES EITHER SIDE OF EACH SPLICE. A MANUFACTURING SPLICE AND ASSOCIATED PROCESSING STREAKS APPEAR ON FRAME 1433. THE 2L POSITION INDICATOR LAMP FAILS TO OPERATE INTERMITTENTLY IN THE FIRST 50 PER CENT OF THE MISSION AND BECOMES ENTIRELY INOPERATIVE IN THE LAST 50 PER CENT.

C. 9L SIDE: INBORAD ROLLER CHATTER IS CONTINUOUS THROUGHOUT THE MISSION. A MINUS DENSITY STREAK 0.05" FROM AND PARALLEL TO THE INBOARD EDGE IS CONTINUOUS FROM FRAME 1 THROUGH FRAME 1500. PLUS DENSITY STREAKS ALONG THE MAJOR AXIS OF THE FILM (PROBABLY PRE-PROCESSING ABRASIONS) ARE INTERMITTENT THROUGHOUT THE MISSION. (EXAMPLE FRAMES 236-249). INBOARD EDGE FOG IS INTERMITTENT FROM FRAME 1168 TO THE END OF THE MISSION.

D. BOTH SIDES: GHOST IMAGES OF ALL POSITION INDICATORS APPEAR SIMULTANEOUSLY AS THE PROPER POSITION IS CORRECTLY RECORDED. PROCESSING STREAKS ARE CONTINUOUS THROUGHOUT THE MISSION. THERE ARE 1824 TITLED FRAMES ON EACH SIDE OF THIS MISSION.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES.

1

-3-

3. POSITIVE:

A. PRINTING AND PROCESSING WERE GOOD.

B. PI SUITABILITY IS FAIR DUE TO THE ADVERSE WEATHER
CONDITIONS.

C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 85 PER CENT
OF THIS MISSION. SCP-1.

S E C R E T

-END OF MESSAGE-

(ALSO PASSED TO CIA WATCH AND)

25X1